

DART SERVICE INSTRUCTION

TO AMEND IIN-D139-799 REV. F AND ICA-D139-799 REV. 5
REF. FAA STC: SR02138SE

1.0 PURPOSE:

The purpose of this DSI is to correct the part number for the cotter pin listed in the Part List in Section 5.0 of IIN-D139-799 Rev. F and Section 62.3 of ICA-D139-799 Rev. 5.

2.0 CHANGE:

Replace the part number as shown below:

QTY. -023	PART NUMBER	DESCRIPTION
X	D139-799-023	ANTI-ROTATION BLOCK KIT

IS:

10	MS24665-155	PIN, COTTER
----	-------------	-------------

WAS:

10	MS24665-115	PIN, COTTER
----	-------------	-------------

3.0 WEIGHT AND BALANCE:

This part number change has a negligible effect on Weight and Balance.

A	NEW ISSUE		RF	12.02.08
REV.	DESCRIPTION		BY	DATE
DESIGN	RF	DART AEROSPACE USA, INC. KENT, WA		
DRAWN	RF			
CHECKED	<i>BS</i>	DRAWING NO.	REV. A	
MFG. APPR.	N/A	DSI 9595	SHEET 1 OF 1	
APPROVED	<i>MM</i>	TITLE	SCALE	
DE APPR.	<i>MM</i>	P/N CORRECTION	NTS	
DATE	12.02.08	COPYRIGHT © 2012 BY DART AEROSPACE USA, INC. THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.		